

TWO TOOTH GASKET SET

In August 1930 FORD changed the size of the steering gear housing counterbore to provide for a better oil seal. The new gasket is thicker by $\frac{1}{32}$ " or to $\frac{1}{8}$ " thick. The outside diameter was increased by $\frac{3}{64}$ " or to $2 \frac{11}{32}$ ". Both gaskets are enclosed so you will have the correct one to use.

